




汉默欧机床测头接线图(无线电传输-发那科系统)



= 24V = 0V
=SKIP X4.7 =COM SKIP